

OFFICIAL INSPECTION REPORT

Continuation Sheet

GLENN COUNTY ENVIRONMENTAL HEALTH DEPARTMENT

225 N. Tehama Street, Willows, CA 95988

Phone (530) 934-6102 FAX (530) 934-6103

Page _____ of _____

Name of Facility / DBA: Cedar Hills Manor	Inspection Date: 5/12/23
Address: 600 N. Humboldt Ave	
Owner/Permitee: P.I Properties	

Comments:

Repair the chipped plaster on the steps inside the pool



Repair the broken pressure gauge next to the chlorine feeder

Repair the broken chlorine feeder.

The pool has been closed since 2019. Maintain closure due to violations. * Submit plans to this department ~~for~~ before any pool construction repairs.*

POOL SHALL REMAIN CLOSED.

call for reinspection.

Received By: 	REHS: 
--------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------